

## EMAC Consigned Component Requirements – R1

- This Document assumes that all components are factory new and purchased from a Franchise Vendor. If any issues with components exist this is the Customer’s Responsibility and may incur additional cost.
- Each component should be individually packaged
- Each package must be labeled with the manufactures part number
- Include a Packing list containing all components and their quantities provided
- EMAC prefers Reels with plenty of feeder length or Trays rather than Tubes.  
(Note: An extra charge maybe incurred for Tubed parts or Cut Tape)  
(Note: Digikey & Mouser both offer Reeling services for Cut Tape)
- Moisture Sensitive Parts should be packaged with desiccant, a moisture indicator card, and sealed (EMAC will not bake parts unless instructed to do so and an extra charge will be incurred)
- EMAC requires Component Overage as specified in the Table below.

Component	Overage Amount
01005 0201 0402	An additional 100% + 50 Extra Pcs <b>Please note: parts must be in a continuous strip</b>
0603	An additional 20% + 20 Extra Pcs
0805	An additional 10% + 20 Extra Pcs
1206 & higher	An additional 10% + 10 Extra Pcs
All other parts:	An additional 5% + 5 Extra Pcs

**Notes:** If a Customer provided Component Package is short of parts to complete the run, EMAC will hold the run and contact the Customer requesting that they facilitate getting the missing parts delivered to EMAC by the next morning. Once the missing parts are received, EMAC will continue the run. If the parts are not received by 10AM the next day, EMAC will pull the run and another run, at additional charge, will need to be scheduled to complete the order.

Any Component overage that are not wasted and not utilized will be returned to the Customer.